

KRO Vehicle Intake Report

Raport preluare vehicul - ID #20868

Poza coperta masina



Identificare vehicul

VIN: 1GYS9GKL6TR299267

Validare VIN: -

Lot: -

Marca: Cadillac

Model: Escalade

Km: 12186

Combustibil: Benzina

Culoare: Negru

An model: 2026

Tip caroserie: Suv

Motor: 5999

Tara provenienta: Canada

Observatii generale

Necesita atentie :check engine light

Checklist tehnic

- Nivel ulei motor: OK
- Nivel antigel: OK
- Nivel lichid frana: OK
- Nivel lichid servodirectie: OK
- Nivel lichid parbriz: OK
- Curele vizibile / accesorii: OK

- Baterie / borne: OK
- Anvelope / jante: OK
- Faruri faza scurta / lunga: OK
- Stopuri / semnalizari: OK
- Martori bord aprinsi: Atentie
- Pornire motor: OK
- Cutie viteze / selector: OK
- Frana de mana / pedala frana: OK
- Parbriz / geamuri / oglinzi: OK
- Chei / acte / accesorii: OK

Inspectie vizuala caroserie si exterior / interior

Zona: Fata / bara / grila

Observatii: Foto 1: Nu se observa o problema clara in fotografie.

Foto 2: Nu se observa o problema clara in fotografie.

Foto 3: Nu se observa o problema clara in fotografie.

Foto 4: Nu se observa o problema clara in fotografie.

Foto 5: Nu se observa o problema clara in fotografie.

Foto 6: Nu se observa o problema clara in fotografie.

Foto 7: Nu se observa o problema clara in fotografie.

Foto 8: Nu se observa o problema clara in fotografie.

Foto 9: Nu se observa o problema clara in fotografie.

Foto 10: Nu se observa o problema clara in fotografie.

Foto 11: Nu se observa o problema clara in fotografie.

Foto 12: Nu se observa o problema clara in fotografie.

Foto 13: Nu se observa o problema clara in fotografie.

Foto 14: Nu se observa o problema clara in fotografie.

Fotografii atasate: 14













Generat automat de KRO Vehicle Intake - 13.06.2026, 11:55:19